Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: AUSTIN 16-19H

Field Name: PARSHALL Well File #: 17416

Date Incident:4/19/2015Time Incident:08:34Facility ID Number:County:MOUNTRAILTwp: 154Rng: 90Sec: 19Qtr:

Location Description:

Submitted By: Matt Richards Received By:

Contact Person: Matt Richards

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
4 Barrels 4 Barrels 4 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/8/2016 Clean Up Concluded: 4/21/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Standing oil was removed with a vac truck and contaminated soil will be remediated.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 4/20/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.